

CAUTION

BUFFING POLISHING MACHINE

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Do not mix incompatible dusts (i.e., steel and aluminum).
- Never start the machine unless all the guards are in place and properly adjusted.
- Beware of moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Dust collection system, if provided, is connected and operational.
- Do not wear gloves, jewelry, or loose clothing.
- Do not reach over moving machinery to activate controls.
- Use proper type of polishing wheel for the material being processed.
- Polish only on side of wheels designed for side polishing.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Ensure that operator is properly trained and has read owner's operation manual.

Note: Immediately report all machinery malfunctions to management.