

CAUTION

DRILL PRESS

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and properly adjusted.
- Beware of moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Do not use dull or damaged drill bits.
- Use clamps, vices, etc. to secure the workpiece to the table.
- Do not grab “quick-change chucks” while rotating, regardless of speed.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read the owner’s operation manual.

Note: Immediately report all machinery malfunctions to management.