

CAUTION

DROP HAMMER

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and properly adjusted.
- Keep the work area clean. Foreign materials may cause poor footing.
- Do not operate machine if unauthorized persons are present.
- Make sure all overhead machinery parts are secured to prevent falling components.
- Use hand tools for all piecework feeding.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owner's operation manual.

Note: Immediately report all machinery malfunctions to management.