

# CAUTION

## ELECTRIC MITER SAW

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and adjusted.
- Beware of moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Make sure the dust collection system, if provided, is connected and operational.
- Clamp workpiece securely before cutting.
- Use proper blade for material being cut.
- Replace dull, cracked, or excessively fouled saw blades.
- Never clamp or wedge guard in open position.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owner's operation manual.

Note: Immediately report all machinery malfunctions to management.