

CAUTION

METAL CUTTING (HORIZONTAL) BAND SAW

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and properly adjusted.
- Beware of all dangerous moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Inspect blades for broken or dull saw teeth, excessive gumming, and fouling.
- Adjust blade guards to cover unused portion of blade.
- Adjust blade tension properly.
- Use saw blade designed for material being cut.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read the owner's operation manual.

Note: Immediately report all machinery malfunctions to management.