

# CAUTION

## METAL WORKING LATHE

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all guards are in place, properly designed and adjusted.
- Be aware of all dangerous moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Do not reach over or around moving machinery to activate controls.
- Securely clamp workpiece.
- Store unused tools in tool racks.
- All personnel must be away from shear table before operation.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owner's operation manual.

Note: Immediately report all machinery malfunctions to management.