

# CAUTION

## RADIAL ARM SAW

### WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and properly adjusted.
- Beware of all dangerous moving machinery parts.
- Keep the work area clean. Foreign materials may cause poor footing.
- Make sure the dust collection system, if provided, is connected and operational.
- Make sure saw gently returns to starting position when released.
- Use a stick or brush to remove small scraps from worktable.
- Use the proper saw blade for the material being cut.
- Replace dull, cracked, or excessively fouled saw blades.
- Do not use abrasive, cutoff, or wire wheels on radial arm saws.
- Saw blade must never travel beyond working edge of table; forward travel stop is properly adjusted.
- When cross-cutting, use workpiece clamps to prevent “kickback” hazards.
- When ripping, kickback dogs must be used and properly adjusted.
- Never exceed the saw blade’s RPM rating.
- Follow manufacturer’s requirements for cutting ferrous and nonferrous metals.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read the owner’s operation manual.

**Note: Immediately report all machinery malfunctions to management.**