

CAUTION

TABLE SAW

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(eye, face, hearing, etc.)

- Never start the machine unless all the guards are in place and properly adjusted.
- Spreader and anti-kickback dogs are properly positioned and functional when cutting wood.
- Make sure the dust collection system, if provided, is connected and operational.
- Keep the work area clean. Foreign materials may cause poor footing.
- Use proper saw blade for material being cut.
- Inspect mounting flanges for damage and proper size.
- Replace dull, cracked, or excessively fouled saw blades or blades with broken teeth.
- Use push blocks/push sticks whenever possible.
- Follow the manufacturer's requirements for cutting ferrous and nonferrous metals.
- De-energize and lockout all energy systems before making adjustments/repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read the owner's operation manual.

Note: Immediately report all machinery malfunctions to management.